




A section of the bodywork drawing office is seen above. Every minute detail is worked out here for those who make the great dies which are used to stamp out the steel panels. The picture on the right shows a special machine which "contours" the body dies: the tracer moving over the top pattern controls the movements of the cutter below.

(Below) The present-day 100-acre car factory of the Austin Motor Company, and the body works in the foreground.



(Below) The Austin factory of 2 1/2 acres in 1905.

